

Important safety information



Dear Siku fans!

In rare cases, our batteries with item number 6711 may present a technical defect. As a result and as a precautionary measure, we are recalling this battery and the three models from the SIKUCONTROL32 range in which this battery is installed:



- **Battery (item no. 6711)**
- **John Deere Tracked Tractor (item no. 6761, 6762 or 6763)**
- **John Deere Tractor 8345R (item no. 6771, 6772 or 6773)**
- **Fendt Front Loader (item no. 6769)**

Under adverse conditions, the defect on the 6711 battery may cause the battery to heat up excessively. As a responsible manufacturer of high-quality toys, we cannot under any circumstances accept reductions in quality and safety.

To exclude any hazards, in particular, the hazard of overheating, we request that you stop using the models any longer, immediately remove the battery from the devices and recycle the battery(ies). Under the statutory provisions of the two-year warranty period, we are pleased to offer you item 6777 SIKUCONTROL32 John Deere with frontloader as a replacement product. If you would like to take advantage of this offer, please return to us the complete product (model incl. charger, hand remote control and battery as well as, if applicable, replacement battery type 6711) with your till receipt, which should not date back more than two years. We will exchange the model for you.

Thank you for your understanding and cooperation!

Your Siku team